


1.open folder



2. If the PC ′ s system is WINDOWS 64 bit ， double click the 

of 9.STM32 to install the program of USB-COM; If the PC′ s system is WINDOWS 32 bit，double click the 

of 9.STM32 to install the program of USB-COM


3,Scan “USB-COM” barcode in the User Guide, then the PC will install the Virtual COM Port program automatically.


IF if automatically install fail ,install it again as the blow steps:

1, Open the computer “device manager”(right click “computer” and select “properties”→select “device manager”)， there is an unrecognized driver “USB Adapter”.



2,select the unrecognized drive, click “right mouse”→choose “update driver software” →choose “install automatically”, then it will install the drive automatically.





3, when install successfully , there will a “COMx” in the computer “device manager”, the”x” represent the Serial number